



LEGEND

| | |
|--|-----------------------------|
| | SITE BENCHMARK |
| | SANITARY MANHOLE |
| | CLEANOUT |
| | STORM MANHOLE |
| | STORM INLET (RECTANGLE) |
| | FIRE HYDRANT |
| | WATER VALVE |
| | IRRIGATION CONTROL VALVE |
| | WATER METER |
| | LIGHT POLE |
| | ELECTRIC TRANSFORMER |
| | ELECTRIC BOX |
| | UTILITY POLE |
| | TELEPHONE MANHOLE |
| | TELEPHONE VAULT |
| | GAS METER |
| | GAS VALVE |
| | HANDICAP PARKING |
| | TRAFFIC SIGNAL MAST |
| | DECIDUOUS TREE |
| | BOLLARD |
| | SIGN |
| | STORM LINE (UNDERGROUND) |
| | SANITARY LINE (UNDERGROUND) |
| | WATER LINE (UNDERGROUND) |
| | GAS LINE (UNDERGROUND) |
| | ELECTRIC LINE (UNDERGROUND) |
| | ELECTRIC LINE (OVERHEAD) |
| | CHAIN LINK FENCE |
| | IRON FENCE |
| | CONCRETE AREA |

NOTES:

1. This is a topographic map. It is not a Land Survey Plat or Improvement Survey Plat. No research of easements, encumbrances or title of record was performed Clark Land surveying Inc.
2. Any underground utilities shown have been located from field survey information and utility locate markings. The surveyor makes no guarantee that the underground utilities shown comprise all such utilities in the area, either in service or abandoned. The surveyor further does not warrant that the underground utilities shown are in the exact location indicated although he does certify that they are located as accurately as possible from the information available. This surveyor has not physically located the underground utilities.
3. BENCHMARK: Chiseled "X" in concrete. Elevation = 681.09' (NAVD 88).
4. Field work for this survey was completed on December 12, 2017
5. BASIS OF BEARINGS: Survey is referenced to Texas State Plane, 4202-Texas North Central Zone.

Clark
Land Surveying, Inc.
www.clarkis.com
177 S. Tiffany Dr., Unit 1 • Pueblo West, CO 81007 • 719.582.1270

Project **170879**
 Drawn By: AMF
 Checked By: RLM

TOPOGRAPHIC SURVEY
 A PORTION OF
 J R BELL SURVEY, ABSTRACT NO. 113123
 CITY OF DALLAS, DALLAS COUNTY, TEXAS

SITE NAME:
 Dallas, TX
 (Home Depot 547)

| No. | Description | By | Date |
|-----|-----------------------------------|-----|-----------|
| 1 | Additional Topography/Invert Data | AMF | 2/14/2018 |